Oil Field Environmental Incident Summary

Responsible Party: knr Roustabout **Well Operator:** MARSHA AZAR **Well Name:** DAVIS STATE 34-36

Field Name: KILLDEER Well File #: 14962

Date Incident: 9/19/2015 Time Incident: 19:12 Facility ID Number:

County: DUNN Twp: 146 Rng: 95 Sec: 36 Qtr:

Location Description:

Submitted By: Greg Krueger Received By:

Contact Person: Greg Krueger

box 210

killder, nd 58640

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 2 Barrels

Brine

Other

Description of Other Released Contaminant:

No additional materials were emitted from the reported incident.

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

their where cattle in pasture but we had hydro- vac and crew out their washing and sucking up contaminated area within an 1 hour after the incident

Areal Extent:

Potential Environmental Impacts:

The scoria around well head and a 10 by 10 grass area on location, were indicative of a reclamation not looking to exceed the 3.5 cubic/yards on the pad, and an additional 15 cu./yds. was collected on the natural erosion area coming away from the pad, and any additional seepage perceived to be

Action Taken or Planned:

Shut well down replaced stuffing box rubbers turn down the Murphy Switch kill tore apart Baird back pressure valve to check for paraffin and scale that might have gotten plugged up in the valve and caused over pressuring of flow line witch we did find some in it. An earthen berm was created on North and West side as a precautionary measure. An increased amount of intervals are planned by the pumper, as simply a precautionary move, to act as visual vigilance to see that the repairs made have the lasting effect intended.

Wastes Disposal Location: Renewable Resources Killdeer N.D (An approved vendor with the Sate Of North Dakota).

Agencies Involved:

D			

Date: 9/22/2015 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a stuffing box leak, remained on location according to the report. NDIC retains oversight.

Date: 9/28/2015 Status: Reviewed - Assigned to Other Agency Author: Wax, Pete

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On site 16:50, 59 degrees, clear light winds. Incident and condition appear accurate. Reference to livestock was made as the pad is in an open-range pasture with cows. Off site 17:10.